



## QUALITIUM ATF VI

**Premium, fully synthetic oil designed for modern automatic transmissions.**

### APPLICATION

- Qualitium ATF VI is designed for modern automatic transmissions in various types of vehicles
- Qualitium ATF VI meet requirements Dexron VI, Mercon LV, JASO-1A LV and many others OEM's specifications .
- it is suitable for systems where ATF oils class Dexron IIIH and Dexron IID is required.
- do not use in transmissions where CVT or DCT oils are recommended

### SPECIFICATIONS

Dexron VI  
Mercon LV  
JASO-1A LV

### MEETS REQUIREMENTS

OEM's specifications - Tabel below

### REPLACEMENT OILS

Mobil ATF Multi-Vehicle  
Castrol Transmax Dexron VI Mercon LV  
Shell Spirax S6 ATF X  
Total Fluide XLD FE  
Motul ATF VI  
Platinum Gear ATF VI Hybrid

### AVAILABLE OIL VOLUMES

1L, 5L, 20L, 205L

### ADVANTAGES

- helps improve fuel economy
- provides consistent shift performance for the life of the vehicle
- extends transmission fluid life and prevents fluid breakdown at higher operating temperatures
- fully synthetic , high quality raw materials
- reduces sludge and varnish build-up
- protects transmission gears and allows them to operate smoothly
- flows well for cold start-up

| Parameters                                        | Value |
|---------------------------------------------------|-------|
| Kinematic viscosity at 100°C (mm <sup>2</sup> /s) | 5,9   |
| Viscosity index                                   | 150   |
| Flash point (COC, °C)                             | 212   |
| Pour point (°C)                                   | -50   |
| Color, visual                                     | red   |

\* The above are typical physicochemical values. The actual physicochemical values are to be found in the laboratory report attached to each batch of the product.

### DETAILS OF THE COMPANY/TECHNICAL DEPARTMENT

Qualitium Sp. z o.o.  
Brzeście Nowe 11B/2, 09-130 Baboszewo

|                                                                                 |
|---------------------------------------------------------------------------------|
| Acura ATF-Z1                                                                    |
| Aisin Warner JWS 3309 (T-IV) & JWS 3324 (WS), AW-1                              |
| Aisin Warner AW-2, PSA 16 350 560 80, VW G 053 001                              |
| Allison C-3 & C-4                                                               |
| Allison TES-295 (only recommend visc @ 100°C >7.0 cSt)                          |
| Allison TES-389                                                                 |
| Allison TES-468                                                                 |
| American Motors ATF +3 (MS7176-E)                                               |
| AML Oil No. 4G43A9A509/AA/S                                                     |
| ATF RED 1, RED 1K                                                               |
| Audi 5 HP LT71141 (ZF 5 HP 18FL/19FL/24A)                                       |
| Audi/VW G 052 025 A2                                                            |
| Audi/VW G 053 025 A2                                                            |
| Audi/VW G 052 162 A1/A2                                                         |
| Audi/VW G 052 162 (ZF LifeguardFluid 5) (ZF No. S671 090 170)                   |
| Audi/VW G 055 005 -A, -A1, -A2, -A6 (ZF LifeguardFluid 6) (ZF No. S671 090 255) |
| Audi/VW G 055 162-A2, -A6 (ZF LifeguardFluid 6 Plus) (ZF No. S671 090 281)      |
| Audi/VW G 060 162 (ZF LifeguardFluid 8) (ZF No. S671 090 312)                   |
| Audi/VW G 052 990                                                               |
| Audi/VW G 055 540 A2                                                            |
| Audi/VW 052 055                                                                 |
| Bentley PY112995PA                                                              |
| BMW JWS 3309 (T-IV)                                                             |
| BMW LA2634                                                                      |
| BMW LT71141 (ZF 5 HP 18FL/19FL/24A)                                             |
| BMW ZF 5HP18FL, 5HP24, 5HP30                                                    |
| BMW 7045E                                                                       |
| BMW ETL 8072B                                                                   |
| BMW ATF 2                                                                       |
| BMW ATF 3+                                                                      |
| BMW ATF 6                                                                       |
| BMW ATF 7                                                                       |
| Bosch TE-ML 09                                                                  |
| CAT TO-2                                                                        |
| Chrysler ATF+, +2, +3 (MS7176E)                                                 |
| Chrysler/Dodge MOPAR AS 68 RC and AS 69 RC (T-IV), JWS 3309                     |
| Chrysler/Dodge/Jeep 05127382AA                                                  |
| Chrysler/Dodge/Jeep 68043742AA                                                  |
| Chrysler/Dodge/Jeep 68157995AA                                                  |
| Chrysler/Dodge/Jeep 68157995AB                                                  |
| Chrysler/Dodge/Jeep Borg Warner 68049954AA                                      |
| Chrysler/Dodge/Jeep 68218925AA and 68218925AB                                   |
| Chrysler/Dodge/Jeep MOPAR SP IV, 68171866AA/68171869AA                          |
| Daewoo LT 71141                                                                 |
| Daihatsu AMMIX ATF D-II                                                         |
| Daihatsu AMMIX ATF D-III SP                                                     |
| DANA OHTM ATF (only recommend visc @ 100°C > 7.0 cSt)                           |
| Esso LT 71141                                                                   |
| FIAT T-IV type, JWS 3309                                                        |
| FIAT 9.55550-AV5                                                                |

|                                                                                                    |
|----------------------------------------------------------------------------------------------------|
| FIAT 9.55550-AV6                                                                                   |
| Ford MERCON®                                                                                       |
| Ford MERCON® LV (FF-WSS-M2C-938A/SF, XT-10 QLV)                                                    |
| Ford ATF C-ML5                                                                                     |
| Ford FNR5 (Mazda M5, XT-9-QMM5)                                                                    |
| Ford WSS M2C 138CJ, 166H                                                                           |
| Ford WSS M2C 922A1, 924A (XT-8-QAW) JWS 3309                                                       |
| Ford/Lincoln/Mercury XT-6-QSP or -DSP (SP)                                                         |
| Ford/Lincoln/Mercury XT-2-QDX (M)                                                                  |
| Ford/Lincoln/Mercury XT-2-QSM (Syn)                                                                |
| Ford ESP-M2C166H, XL-12                                                                            |
| Fuso ATF-II                                                                                        |
| Fuso ATF-SPIII                                                                                     |
| Fuso ATF-A4                                                                                        |
| GM9986195 (Aisin AW-1, JWS 3309)                                                                   |
| GM TASA                                                                                            |
| GM DEXRON®-II                                                                                      |
| GM DEXRON®-IID                                                                                     |
| GM DEXRON®-IIE                                                                                     |
| GM DEXRON®-IIIG                                                                                    |
| GM DEXRON®-IIIH                                                                                    |
| GM DEXRON®-VI                                                                                      |
| GM 1940700                                                                                         |
| GM 1940767                                                                                         |
| GM 21005966                                                                                        |
| GM 22717466                                                                                        |
| GM 88900925                                                                                        |
| GM 9986195                                                                                         |
| GM 93160393                                                                                        |
| GM Transfer Case (AutoTrak II)                                                                     |
| GM/GMC/Opel/Saturn AW1                                                                             |
| GM/GMC/Opel/Saturn VI                                                                              |
| GM/GMC/Opel/Saturn 88863400                                                                        |
| GM/GMC/Opel/Saturn 88863401                                                                        |
| Hino Blue ribbon ATF                                                                               |
| Honda ATF-Z1 (except in CVTs)                                                                      |
| Honda DW-1                                                                                         |
| Honda Type 3.0                                                                                     |
| Honda Type 3.1 : 08263-999-01HE (EU), 08200-9017 (USA) (ZF LifeguardFluid 9) (ZF No. AA01.500.001) |
| Honda Ultra HEVF-Type 1                                                                            |
| Hyundai/Kia SP-IV (00232-1904/04500-00115)                                                         |
| Hyundai/Kia SP-IV M (SP4-M)                                                                        |
| Hyundai/Kia SPH-IV                                                                                 |
| Hyundai/Kia SP-IV-RR                                                                               |
| Hyundai/Kia SP-III                                                                                 |
| Hyundai/Kia Dex-II/ SP-II                                                                          |
| Hyundai/Kia JWS 3314                                                                               |
| Hyundai/Kia NWS 9638                                                                               |
| Hyundai/Kia 040000C90SG                                                                            |
| Hyundai/Kia NUMM040 CH20 Red-1                                                                     |

|                                             |
|---------------------------------------------|
| Idemitsu K17 3100 PL085                     |
| ISUZU ATF WSI                               |
| ISUZU BESCO ATF-II                          |
| ISUZU BESCO ATF-III                         |
| ISUZU 08200-9001                            |
| Jaguar ATF 3403 M115, ATF 3403-M115,        |
| Jaguar ATF LT71141, ZF 5HP24                |
| Jaguar JLM20238                             |
| Jaguar ATF 3403 JLM20238,                   |
| Jaguar K17                                  |
| Jaguar JLM 20292                            |
| Jaguar Fluid 8432                           |
| Jaguar 02JDE26444                           |
| Jaguar WSS-M2C922A1                         |
| JASO M315-2013 1A                           |
| JASO M315-2013 1A-LV                        |
| JASO M315-2013 2A                           |
| JEEP ATF+3                                  |
| KIA ATF SP-II, SP-III, SP-IV, SP-IVM, Red 1 |
| Land Rover TYK500050                        |
| Land Rover LR0022460                        |
| Land Rover LR023288                         |
| Lexus JWS 3309                              |
| MAN 339A                                    |
| Maserati 231603                             |
| Mazda ATF D-II                              |
| Mazda ATF M-III                             |
| Mazda ATF M-V                               |
| Mazda ATF FZ                                |
| Mazda ATF A7                                |
| Mazda ATF F-1                               |
| Mazda ATF S-1                               |
| Mazda ATF N-1                               |
| MAZDA ATF 3317                              |
| MB ZF 4HP20                                 |
| MINI COOPER T-IV                            |
| Mitsubishi Diaqueen SK                      |
| Mitsubishi Diaqueen SP-II                   |
| Mitsubishi Diaqueen SP-III                  |
| Mitsubishi Diaqueen SP-IV                   |
| Mitsubishi Diaqueen AW                      |
| Mitsubishi Diaqueen J2                      |
| Mitsubishi Diaqueen J3                      |
| Mitsubishi Diaqueen ATF-MA1                 |
| Mitsubishi Diaqueen ATF PA                  |
| NAG 1 (Chrysler, Jeep, Cherokee)            |
| Nissan Matic Fluid C                        |
| Nissan Matic Fluid D                        |
| Nissan Matic Fluid J                        |
| Nissan Matic Fluid K                        |

|                                                            |
|------------------------------------------------------------|
| Nissan Matic Fluid P                                       |
| Nissan Matic Fluid S                                       |
| Nissan Matic Fluid W                                       |
| Opel/GM 19 40 700                                          |
| Opel/GM 19 40 767                                          |
| Opel/GM 21005966 Transaxle                                 |
| Opel/GM 22 17466                                           |
| Opel/GM 88900925                                           |
| Opel/GM 9986195                                            |
| Peugeot ZF 4HP20                                           |
| Peugeot/Citroen Z 000169756                                |
| Peugeot/Citroen (PSA) AL4 Automatic gearbox oil (#9730.AE) |
| Porsche ZF 5HP19FL, ZF 5HP20, LT71141                      |
| Porsche ATF 3403-M115,                                     |
| Porsche T-IV (JWS 3309)                                    |
| Porsche 000 043 205 09                                     |
| Porsche 999 917 547 00 (A2)                                |
| Porsche 000 043 205 28                                     |
| Porsche Z 000169756                                        |
| PSA B71 2340                                               |
| Renault DPO/AL4                                            |
| Renault Matic D2                                           |
| Renault Samsung SATF-D                                     |
| Saab T-IV (JWS 3309)                                       |
| Saab 93 165 147                                            |
| Saab 93 160 393                                            |
| Saab Power Steering Fluid 2634, 45 30 09 800, 93160548     |
| Saturn T-IV (JWS 3309)                                     |
| Scion (all vehicles)                                       |
| Shell 3403, M115, LA 2634                                  |
| Shell M-1375.4                                             |
| Shell L 12108                                              |
| Ssang yong DSIH 5M-66                                      |
| Subaru ATF                                                 |
| Subaru K0140Y0700                                          |
| Subaru ATF 5AT                                             |
| Subaru DEXRON®-II                                          |
| Subaru ATF, ATF HP                                         |
| Subaru Opel Original ATF 09117946/93160393                 |
| Suzuki ATF AW-1                                            |
| Suzuki AT OIL 5D06                                         |
| Suzuki ATF 2326                                            |
| Suzuki ATF 2384K                                           |
| Suzuki JWS 3309                                            |
| Suzuki ATF 3314                                            |
| Suzuki ATF 3317                                            |
| Texaco 7045-E                                              |
| Texaco 8072B                                               |
| Texaco N402                                                |
| Toyota ATF D-II                                            |

|                                                 |
|-------------------------------------------------|
| Toyota ATF D-III                                |
| Toyota ATF T-III                                |
| Toyota ATF T-IV                                 |
| Toyota ATF WS                                   |
| Vickers M2950-S, I-286-S                        |
| Voith 55.6335.xx (G607)                         |
| Volvo 97325                                     |
| Volvo 97335                                     |
| Volvo CE 97340                                  |
| Volvo PN 1161521                                |
| Volvo PN 1161540/1161640                        |
| Volvo PN 31256774/31256675                      |
| Volvo PN 1161621                                |
| VW 5 HP (ZF 5 HP 30)                            |
| VW 5HP (18FL, 30)                               |
| VW 5HP (19FL, 24A)                              |
| VW G-055-025 A2 (JWS 3309)                      |
| VW G055 540 (A2)                                |
| VW G 052 162 (ZF LifeguardFluid 5)              |
| VW G 055 005-A, -A2 (ZF LifeguardFluid 6)       |
| VW G 055 162-A2, -A6 (ZF LifeguardFluid 6 Plus) |
| VW G 060 162 (ZF LifeguardFluid 8)              |
| VW TL 521 62                                    |
| ZF all 3 & 4 speed transmission                 |
| ZF 6 speed transmissions                        |
| ZF 8 speed transmissions                        |
| ZF 9 speed transmissions                        |
| ZF TE-ML 05L                                    |
| ZF TE-ML 09                                     |
| ZF TE-ML 11A, 11B                               |
| ZF TE-ML 21L                                    |
| Service-fill for 8 and 9 speed step-ATs         |
| <b>eMobility Claims</b>                         |
| Ford Escape Hybrid eCVT                         |
| Honda e:HEV                                     |
| Honda iMMD                                      |
| Jatco JR712E                                    |
| Mazda SKYACTIVE-HYBRID                          |
| Nissan Altima Hybrid                            |
| Tesla Model S, Model 3, and Model X             |
| Toyota THSII/Toyota Prius                       |
| Toyota THS 5th Gen. / Toyota Noah, Voxy etc.    |

**Not to be used for DCT or CVT applications**